

DELL Inspiron 15R N5010, M5010 laptop fan / cooler

Generuota 2025-08-17



Name	Description
Condition	New
Number of contacts	3 pin
Side	CPU
CODE	DE-17F
MODELS	DELL Inspiron 15R N5010, M5010, M501R, 5010
MANUFACTURER CODE	DFB451005M20T, 23.10377.001, 03T25W, 0K28PW, 0NC4TX, AB7205HX-GC1, 0NC4TX, 23.10378.001, 60.4HH13.002, K74YV, MF60120V1-B020-G99, 03T25W, KDB0705HA, XS10N05YF05VBJ, RF2M7, 23.10379.001, F91G, KSB0505HA-9L60, NC4TX, XS10N05YF05V-BJ001, 0K74YV, 23.10377.001, 3T25W, K28PW, MF60100V1-Q000-G99, 0K28PW, DFB451005M20T, 00P4JP, 0P4JP
SERVICE	COMPUTER REPAIRS ALL OVER LITHUANIA! Attention those in a hurry: we can pick up your computer for repair ourselves and return it repaired via courier (throughout Lithuania). Order the service, hand over the parcel to the courier, and upon receiving the repaired device, you can pay for the repair in cash. Convenient and safe!