

DELL Inspiron 15R N5010, M5010 laptop fan / cooler

Generuota 2025-06-14



Number of contacts 3 pin

Side CPU

Condition New

CODE DE-17F

MODELS DELL Inspiron 15R N5010, M5010, M501R, 5010

MANUFACTURER CODE

DFB451005M20T, 23.10377.001, 03T25W, 0K28PW, 0NC4TX, AB7205HX-GC1, 0NC4TX, 23.10378.001, 60.4HH13.002, K74YV, MF60120V1-B020-G99, 03T25W, KDB0705HA, XS10N05YF05VBJ, RF2M7, 23.10379.001, F91G, KSB0505HA-9L60, NC4TX, XS10N05YF05V-BJ001, 0K74YV, 23.10377.001, 3T25W, K28PW, MF60100V1-Q000-G99, 0K28PW, DFB451005M20T, 00P4JP, 0P4JP

SERVICE

COMPUTER REPAIRS ALL OVER LITHUANIA! Attention those in a hurry: we can pick up your computer for repair ourselves and return it repaired via courier (throughout Lithuania). Order the service, hand over the parcel to the courier, and upon receiving the repaired device, you can pay for the repair in cash. Convenient and safe!