

DELL Latitude 3590, E3590, Inspiron 15 5570, 5575 laptop fan / cooler

Generuota 2025-06-07



Condition	New
Number of contacts	4 pin
Side	CPU
CODE	DE-25F
MODELS	DELL Latitude 3590, E3590, L3590 Inspiron 15 5570, 5575, 17 3780, 15 5570, P75F / Vostro 3590, 15-5570, 3590, E3590, 15-3593, 3580, 3581, 17-3780, 5570, 5575, 5770, G3 3579, LOKI G 15 CFL BTX, 5775 LOKI 17 AMD BTX, 5770, LOKI 17 INTEL BTX, 5575 LOKI 15 AMD BTX, 5570 LOKI 15 INTEL BTX, 3781 N3 LOKI 17 KBL BTX, 3780 N3 LOKI 17 WHL CNL BTX, 3581 N3 LOKI 15 KBL 2SP BTX, 3580 N3 LOKI 15 WHL CNL 2SP BTX Latitude3590 LOKI L 15 CTO, 3590 LOKI L 15 BTXVostro Notebooks3581 V3 LOKI15 KBL2SP BTX, 3580 V3 LOKI15 WHL CNL2SP BTX DELL inspiron 3593
MANUFACTURER CODE	OFX0M0 FX0M0, FK3A, DFS1503055POT, DC28000K9F0, DC28000K9D0, CN-OFX0M0, ONPFW6, DC28000K8D0
SERVICE	COMPUTER REPAIRS ALL OVER LITHUANIA! Attention those in a hurry: we can pick up your computer for repair ourselves and return it repaired via courier (throughout Lithuania). Order the service, hand over the parcel to the courier, and upon receiving the repaired device, you can pay for the repair in cash. Convenient and safe!