


HP Pavilion 15, 15-E series laptop DC jack

Generuota 2026-03-03



Name	Description
Jack type	Soldered
Jack diameter	4.5x3.0 mm
CODE	(HP-11L)
Number of contacts	
Cable length	
MODELS	HP Pavilion 15, 15-E, 17-E serijos, 15-E006ea15-E006sa15-E008ea15-E008sa15-E009ea15-E010sa15-E011sa15-E045sa15-E046sa15-E047sa15-E050ea15-E050sa15-E054sa15-E072ea15-E072sa15-E073ea15-E073sa15-E078ea15-E078sa15-E081ea15-E081sa15-E090ea15-E092ea15-E096sa15-E044sa15-E043sa15-E042sa15-E012sa15-E013sa15-E014sa15-E020sa15-E021sa15-E022sa15-E026sa15-E027sa15-E027tx15-E028sa15-E028tx15-E030ea15-E031sa15-E034ea15-E034sa15-E036sa15-E041sa15-E097sa15-E15-E00017-E17-E00017-E031sa17-E032sa17-E101sa17-E105sa17-E153ea
SERVICE	We carry out computer repair work, replace broken, non-contact sockets with new ones within 1-2 days. days.
Warranty	12 months / 24 months if our specialists change
MANUFACTURER CODE	709802-SD1, 709802-FD1