

**DELL Vostro 1014, 1015, 1018, 1088 laptop fan / cooler**

Generuota 2026-04-16



Name	Description
Side	CPU
Condition	New
Number of contacts	4 pin
CODE	DE-10F
MODELS	DELL Vostro 1014, 1015, 1018, 1088, PPP38L, PP38L, OY34KC, Y34KC
MANUFACTURER CODE	XS10N05YF05VBJ, DFS551305MCOT, Y34KC, DFS491105MHOT, 3CVM8FAWI00 OY34KC, OY34KC, Y34KC, 3CVM8FAWI00, ZB0506PGV1-6A, PP38L, Y34KC, FS491105MHOT, XR-DE-1014FAN, M408C, 3CVM8FAW120FC99, XS10N05YF05VBJ, DFS531205HCOT, OY34KC, B3561-1.13.V1.F.GN F972
SERVICE	COMPUTER REPAIRS ALL OVER LITHUANIA! Attention those in a hurry: we can pick up your computer for repair ourselves and return it repaired via courier (throughout Lithuania). Order the service, hand over the parcel to the courier, and upon receiving the repaired device, you can pay for the repair in cash. Convenient and safe!