

DELL Inspiron 15R 3521, 15-3521, 3537, 3721, 3737, 5521, 5537, 5721 laptop fans / coolers

Generuota 2025-06-15



Condition	New
Number of contacts	3 pin
Side	CPU
CODE	DE-12F
MODELS	DELL Inspiron 15R 3521, 15-3521, 3537, 3721, 3737, 5521, 5537, 5721, 5735, 5737, Inspiron 17, 17R 15R-3521, 15-R 3521, 15-G M531R, 5535
MANUFACTURER CODE	DFS470805CL0T, DC28000C8A0, SPS-753894-001, 074X7K, EF60070S1-C140-G9A
SERVICE	COMPUTER REPAIRS ALL OVER LITHUANIA! Attention those in a hurry: we can pick up your computer for repair ourselves and return it repaired via courier (throughout Lithuania). Order the service, hand over the parcel to the courier, and upon receiving the repaired device, you can pay for the repair in cash. Convenient and safe!