


HP Compaq 6510B, 6515B, 6520S, 6710b, 6710s, 6715b aušintuvas

Generuota 2025-06-08



Side	CPU
Warranty	6 / 12 (if our specialists change) month.
CODE	HP-25F
Number of contacts	3 pin
MODELS	HP Compaq 6510B, 6515B, 6520S, 6710b, 6710s, 6715b, 540, 541, 550, 6530B, 6520S, 6530S, 6531S, 6535S, 6820s, 6720s, 6520s, 6515b, 6510b, 6830s, NX6330, 6730b, NX6325, NX6320, NX6315, NX6310, NC6320, NC6310, 6735b, 6530b, 6735s, 6730s, 6535s, 6531s, 6530s, 6715s, 6715b, 6710s, 6710b
MANUFACTURER CODE	443917-001 UDQFRPH55C1N, DFB451005M20T, 443917-001 F8, 6043B0024701, DFB451005M20T, 6033B0006301, 431312-001, PF4901AFN002, UDQFRPH55C1N, 112812A, M408C, XS10N05 YF05V-BJ001, DFS531005MCOT
SERVICE	KOMPIUTERIŲ REMONTAS VISOJE LIETUVOJE! Dėmesio skubantiems: kompiuterį remontui galime paimti patys ir grąžinti suremontuota per kurjerį (visoje Lietuvos teritorijoje). Užsisakykite paslaugą, perduokite kurjeriui siuntinį, o sulaukę sutaisyto įrenginio už remontą galėsite atsiskaityti grynais. Patogu ir saugu!